


Potential Issue:




If I want to use a 45° weir box at the rear corner of the Pentagon, the more holes in it, the more it will noticeably cut down on available space in the display


Original:

bean animal 1 2 3 returns from sump 4 5


UV closed loop 6 7




→ UV sterilizer



Alternative #1



Alternative #2



New concern: if one return pump were to fail, could the Y coupler therefore compromise the other?

