



This is what I see in the GHL software on my computer. You can see the pump is communicating and has an option to disconnect but yet in the menu bar it shows "not connected", but it IS!

KH Director Initial Setup (Part 1)

Devices view help tools Extras Backup and restore Communication

Connect Disconnect Administrate Connection Settings

Update view Save changes

youtube.com is now full screen Exit Full Screen (Esc)

ProfiLux 4

- General
- Illumination
- Processes
- Dose overview
- Extras
- VorTech overview
- Probe/sensor controls
- Display
- System
- Programmable logic
- Email notification (ProfiLux)

ProfiLux 4 - General ProfiLux 4 - System

System report ...

ProfiLux Acoustic Bus (PAB)

Assign devices ...

System reset

Property	Value
Name	ProfiLux 4
Class	ProfiLux 4
Version	7.12
Address	1
PAB-Address	17
Serialnumber	170119034
Extension slots	3
Level inputs	4
Sensor 1	pH-value

Firmware update ...

Configuration ...

Click on the function to change it

COM	Interface	Function
1	Serial	Standard

This is a screen print from the GHL video of what I should see in the left hand menu box.

ProfiLux 4

GHL Doser 2

ProfiLux Mini/Light USB

ProfiLux 4

5:36 / 6:33

Scroll for details